



5555 Telegraph Road Los Angeles, CA 90040

Tel: 213 838-1600 Fax: 213 722-8251 REPORT NUMBER: 720210-3R

DATE: 12/24/96 PAGE 1 OF 12

REVISED DATE: 03/04/97

CLIENT:

DOC'S MARKETING CORPORATION

2343 Calle Alucema

Thousand Oaks, CA 91360

SUBJECT:

METAL/WOOD SCREW (150 SP)

REFERENCES:

Conferences and correspondence with Mr. Forrest Dockery commencing September

18, 1995.

SAMPLE ID:

The following specimens were randomly sampled at Doc's Marketing Corporation, 5158 Goldman Ave. Unit A, Moorpark, CA 93021, by an SGS United States Testing Co. representative on October 7, 1996:

• 225 ea, 2¾-inch long, nominal, heat-treated, plated, 1018 steel, ceiling suspension fasteners, Part Number 150SP. Each fastener consisted of a 1½-inch long threaded portion (0.19-inch shank diameter; 0.25-inch thread diameter), a 0.5-inch diameter by 0.08-inch thick washer portion, a 0.21-inch diameter by 0.6-inch long shank portion and a 0.08-inch thick by 0.5-inch long flattened, eyelet portion with a 0.18-inch diameter hole. The underside of the collar portion had a fan blade appearance and the top had four lines radiating from the center (See drawing in the Appendix).

The Client submitted 22-gauge, corrugated, galvanized, sheet metal sections and identified them as being manufactured by Verco, ICBO #2078.

The Rockwell C hardness of the sampled fasteners was 39, as determined by Metal Control Laboratories, Inc. in Montebello, CA, and witnessed by SGS U.S. Testing Company personnel, on November 26, 1996.

The chemical composition of a specimen taken from the sampled lot was determined by the Client and the report, from MGF Wire Processing Industries, Inc., is included in the Appendix.

SIGNED FOR THE COMPANY:

Marco Tachiquin Test Engineer

Member of the SGS Group

David Pereg Manager, Engr. Dept.

ANALYTICAL SERVICES • PERFORMANCE TESTING • STANDARDS EVALUATION • CERTIFICATION SERVICES

SGS U.S. TESTING COMPANY INC. REPORTS ARE FOR THE EXCLUSIVE USE OF THE CLIENT TO WHOM THEY ARE ADDRESSED. ANYONE RELYING ON SUCH REPORTS SHOULD UNDERSTAND ALL OF THE DETAILS OF THE ENGAGEMENT. REPORTS REFLECT RESULTS ONLY OF THE STANDARDS OR PROCEDURES IDENTIFIED TO THE TESTS CONDUCTED AND ARE LIMITED TO THE STANDARDS FOR PROCEDURES IDENTIFIED TO THE TESTS CONDUCTED AND ARE LIMITED TO THE STANDARDS OR PROCEDURES IDENTIFIED TO THE TESTS CONDUCTED AND ARE LIMITED TO THE SAMPLES RESULTS RESULTS WAY NOT BE INDICATIVE OF THE QUALITIES OF THE LOT FROM WHICH THE SAMPLE WAS TAKEN, SGS U.S. TESTING COMPANY INC. HAS NOT CONDUCTED ANY QUALITY CONTROL PROGRAM FOR THE CLIENT, NEITHER THE NAME, SEALS, MARKS NOR INSIGNIA OF SGS U.S. TESTING COMPANY INC. MAY BE USED IN ANY ADVERTISING OR PROMOTIONAL MATERIALS WITHOUT THE PRIOR WRITTEN APPROVAL OF SGS U.S. TESTING COMPANY INC. THIS REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE WRITTEN PERMISSION OF THE SGS U.S. TESTING COMPANY INC. SAMPLES NOT DESTROYED IN TESTING ARE DISPOSED OF AFTER 30 DAYS.



DATE: 12/24/96 PAGE 2 OF 12

REVISED DATE: 03/04/97

**CLIENT: DOC'S MARKETING CORPORATION** 

SAMPLE ID: (CONT.) The following basic production procedure was outlined by the Client (See Photographs in the Appendix):

- 1. 1018 steel from wound wire coils is inserted into a forming machine. \*
- 2. The forming machine cuts the rolled steel to the proper size to create washered "blanks."\*
- 3. The blanks are further processed in other machines that form the threads, shape the heads, and punch/drill a hole in each fastener head. \*
- 4 Fasteners are then sent out to a subcontractor for heat treatment, and plated with Zinc II, giving them a yellow or gold appearance.
- 5. Upon return of lot from heat treatment/plating, several fasteners are selected at random for examination. Between 3 and 4 fasteners out of each 1,000 pounds is tested by inserting into a section of 20-gauge sheet metal.
- 6. Case hardness, per specification, is expected to be between 4 and 8 mils.
- 7. Case hardness is verified by inserting selected fasteners into 20-gauge sheet metal. Fasteners are then impacted with a hammer and visually inspected. Fasteners should bend at least 45 degrees without shearing into two or more pieces. \*
- \* These procedures were witnessed by the SGS U.S. Testing Company representative on October 7, 1996.



DATE: 12/24/96 PAGE 3 OF 12

REVISED DATE: 03/04/97

**CLIENT: DOC'S MARKETING CORPORATION** 

## SUMMARY OF RESULTS:

Substrate	Orientation	Average Maximum Load (Ibs)	Average Deflection (in)
Doug-Fir wood	Tensile	980	0.375
	Shear	300	0.789
	45 degrees	625	0.797
22 gauge metal (0.030-inch average thickness)	Tensile	455	0.654
	Shear	715	1.555
	45 degrees	510	0.798

PROCEDURE:

Fifteen fasteners were drilled into the 2-inch edge of a 2 X 6 inch wooden beam. The beam was secured so that the fasteners were in a vertical position to the fixed table of an Instron testing machine. Each fastener was then individually pulled in tension at a crosshead separation rate of 0.5-inch per minute until failure and the maximum load and deflection were recorded.

The test was repeated on wood with the fasteners in a horizontal position (Shear) and at a 45° angle and on 22-gauge corrugated galvanized steel sections in all three orientations (See Figure Nos. 1 - 6).

## Notes:

- The specific gravity of the wood used in testing was 0.46.
- The fasteners were drilled into the wood and metal without pre-drilling.
- The steel and fasteners were conditioned for a minimum of 40 hours at 73°F and 50% relative humidity prior to testing.
- Testing was performed at 73°F, 50% relative humidity.



DATE: 12/24/96 PAGE 4 OF 12

REVISED DATE: 03/04/97

**CLIENT: DOC'S MARKETING CORPORATION** 

PROCEDURE: (CONT.)




Figure No. 1

Figure No. 2

Figure No. 3




Figure No. 4

Figure No. 5

Figure No. 6

TEST DATES:

Between December 9 and 10, 1996



DATE: 12/24/96 PAGE 5 OF 12

REVISED DATE: 03/04/97

**CLIENT: DOC'S MARKETING CORPORATION** 

RESULTS:		Maximum	Deflection
	<u>Specimen</u>	Load (lbs)	(in)
	Mari Tracil		
	<u>Wood, Tensile</u> 1*		0.550
		900	0.550
	2 3*	1,020	0.521
	4	900 940	0.321
	5 5	1,020	0.368
	6*	1,020	0.421 0.321
	7	1,050	0.321
	/ 8*	1,000	0.315
	9*	1,080	0.356
	10*	960	0.316
	. 11	960	0.364
	12	900	0.311
	13	930	0.382
	14	940	0.326
	15	<u>1,040</u>	0.364
	Average	980	0.375
	Ü		
	Wood, Shear		
	1*	235	0.797
	2*	530	1.321
	3*	300	0.865
	4*	290	1.070
	5*	220	0.706
	6*	280	0.536
	7	690	1.313
	8*	230	0.879
	9*	235	0.693
	10*	240	0.670
	11*	260	0.491
	12*	270	0.581
	13*	235	0.491
	14*	190	0.740
	15*	<u>290</u>	<u>0.680</u>

Average

0.789

300

<sup>\*</sup> Failure occurred as a result of the fastener breaking in two at the washer. All other failures occurred as a result of the fastener pulling out of the wood.



DATE: 12/24/96 PAGE 6 OF 12

REVISED DATE: 03/04/97

**CLIENT: DOC'S MARKETING CORPORATION** 

RESULTS: (CONT)	<u>Specimen</u>	Maximum <u>Load (lbs)</u>	Deflection (in)
	Wood, 45 deg	<u>rees</u>	
	1	840	0.683
	2	750	0.881
	3	420	0.687
	4	740	0.767
	5	800	0.918
	6	510	0.705
	7	550	0.874
	8	380	0.547
	9	780	0.997
	10	535	0.796
	11	510	0.699
	12	720	0.891
	13	635	1.040
	14	585	0.828
	15	620	0.642

Average

All failures occurred as a result of the fastener pulling out of the wood.

0.797

22-gauge stee	el, Tensile	
1	480	0.839
2	450	0.670
3	450	0.583
4	450	0.585
5	470	0.652
6	450	0.647
7	440	0.593
8	440	0.567
9	410	0.661
10	450	0.581
11	460	0.621
12	480	0.624
13	470	0.647
14	490	0.682
15	<u>440</u>	<u>0.860</u>
Average	455	0.654

625

All failures occurred as a result of the fastener pulling out of the metal.



DATE: 12/24/96 PAGE 7 OF 12

REVISED DATE: 03/04/97

**CLIENT: DOC'S MARKETING CORPORATION** 

RESULTS: (CONT)	<u>Specimen</u>	Maximum Load (lbs)	Deflection (in)
	22-gauge steel, 9 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15	685 650 750 700 670 700 750 810 770 740 740 730 670 670	1.343 1.417 1.645 1.460 1.848 1.527 1.548 1.478 1.567 1.670 1.534 1.455 1.609 1.693 1.526
	Average  22-gauge steel, 4  1  2  3  4  5  6  7  8  9  10  11  12  13  14  15  Average	715  45 degrees 510 550 550 540 560 540 550 560 520 380 380 460 500 510 510	0.895 0.838 0.873 0.846 0.840 0.887 0.661 0.765 0.819 0.948 0.790 0.722 0.727 0.652 0.706 0.798

All failures occurred as a result of the fastener pulling out of the metal.